Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 1907

Make Honda Date 22/10/2021

 H
 Model
 Jazz
 Service Advisor

 Tel
 M
 Registration
 WF62YFL
 MOT Due

W Chassis No SHHGG6880DU006207 Inspected By Hristo Klecharov

Mileage 56844

		Comments / Recommendations	Net	VAT	Total
E	ngine Bay				
G	Battery State of Health				
G	Coolant Level				
G	Power Steering Fluid Level				
G	Brake Fluid Level	176°C			
G	Washer Bottle Level				
G	Engine Oil Level				
G	Oil Contamination				
E	ngine Running				
G	Starts				
G	Engine Running				
G	Engine Smoking				
G	Engine Bay Noise				
G	Exhaust Condition (no leaks & secure)				
D	ynamic Operations				
G	Brake Test				
G	Hand Brake Test				
G	Static Gear Selection (engine running)				
G	1st & Reverse Drive Test				
G	Clutch / Auto Drive take up				
G	Steering				
U	Suspension Noise / Ride Height				
G	Aircon (excl. temp & gassing)				
Α	Sat Nav (excl.functionality)	N/A			
G	Ice Operates (excl. functionality)				
G	Central Locking (excl. Key Fob)				
G	Windows				
G	Wipers/Washers				
G	Roof Electrics				
G	Horn				
G	Lights				
G	Indicators				
D	ashboard Checks				
G	Engine Management Light				
G	ABS Warning Light				
G	Brake Wear Indicator Light				
G	Oil Warning Light				
G	Airbag Waring Light				
In	terior Checks				
G	2 Keys				
G	Locking Wheel Nut				
G	Handbook				
G	Vehicle has Fuel (20 miles				
	minimum)				

Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 1907

> Make Honda Date 22/10/2021

Model Jazz Н Service Advisor WF62YFL Tel Registration MOT Due M

Chassis No SHHGG6880DU006207 Inspected By **Hristo Klecharov** W

> Mileage 56844

	Net	VAT	Total	
G Tyre Repair Kit				
A Tool Kit	N/A			
Documentation				
G V5 Registration Certificate				
G Valid MOT				
G HPI Checked				
G No Outstanding Safety Recalls				
	Total	0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer Size	Comments/Recommendations	
G N/S Front	7.0			
G N/S Rear	7.0			
G O/S Front	7.0			
G O/S Rear	7.0			
R Spare	0.0			

Photos





Locking Wheel Nut - Image 1 of 1





Vehicle has Fuel (20 miles minimum) -



Tyre Repair Kit - Image 1 of 1



V5 Registration Certificate - Image 1 of 1



Customer Signature_

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.