Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 5097

Make Abarth Date 20/11/2024

 H
 Model
 595
 Service Advisor

 Tel
 M
 Registration
 CF21XKT
 MOT Due

W Chassis No ZFABF11H6NJF39784 Inspected By George

Mileage 30934 VHC Type PDI Check

		Comments / Recommendations	Net	VAT	Total
Engine E	Зау				
	State of Health				
G Coolant I	Level				
G Power St	teering Fluid Level				
G Brake Flu	uid Level				
G Washer I	Bottle Level				
G Engine C	Oil Level				
G Oil Conta	amination				
Engine F	Running				
G Starts					
G Engine R	Running				
G Engine S	Smoking				
G Engine B	Bay Noise				
	Condition (no leaks				
& secure)				
Dynamic	Operations				
G Brake Te	est				
G Hand Bra	ake Test				
G Static Ge (engine r	ear Selection running)				
G 1st & Re	verse Drive Test				
G Clutch / /	Auto Drive take up				
G Steering					
G Suspens Height	ion Noise / Ride				
	excl. temp & gassing)				
G Sat Nav	(excl.functionality)				
functiona	* *				
Fob)	ocking (excl. Key				
G Windows					
G Wipers/V					
G Roof Ele	ctrics				
G Horn					
G Lights					
G Indicator	S				
Dashboa	ard Checks				
G Engine M	Management Light				
G ABS Wa	rning Light				
G Brake W	ear Indicator Light				
G Oil Warn	ing Light				
G Airbag W	aring Light				
Interior (Checks			•	•
G 2 Keys					
G Locking \	Wheel Nut				
G Handboo					

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 5097

> Make Abarth Date 20/11/2024

Model 595 Service Advisor Н

Registration CF21XKT MOT Due Tel M

ZFABF11H6NJF39784 Inspected By W Chassis No George Mileage 30934 VHC Type **PDI Check**

	Comments / Recommendations	Net	VAT	Total
G Vehicle has Fuel (20 miles minimum)				
G Tyre Repair Kit				
G Tool Kit				
Documentation				
G V5 Registration Certificate				
G Valid MOT				
G HPI Checked				
G No Outstanding Safety Recalls				
	Total	0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer Size	Comments/Recommendations
G N/S Front	7.0		
G N/S Rear	7.0		
G O/S Front	8.0		
G O/S Rear	8.0		
G Spare			


Photos

Battery State of Health - Image 1 of 1



Brake Fluid Level - Image 1 of 1






Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1





Customer Signature	The work outlined in this report has been brought to my attention
	-

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.