Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 4968

Make Volvo Date 2024-10-23

 H
 Model
 XC40
 Service Advisor

 Tel
 M
 Registration
 LV20JFG
 MOT Due

W Chassis No YV1XZ15VDL2341320 Inspected By Andy Underhill

Mileage 28829 VHC Type PDI Check

	Comments / Recommendations	Net	VAT	Tota
Engine Bay				
Battery State of Health				
Coolant Level				
Power Steering Fluid Level				
Brake Fluid Level				
Washer Bottle Level				
Engine Oil Level				
Oil Contamination				
ngine Running		1	1	1
Starts				
Engine Running				
Engine Smoking				
Engine Bay Noise				
Exhaust Condition (no leaks				
& secure)				
Dynamic Operations				
Brake Test				
Hand Brake Test				
Static Gear Selection (engine running)				
1st & Reverse Drive Test				
Clutch / Auto Drive take up				
Steering				
Suspension Noise / Ride Height				
Aircon (excl. temp & gassing)				
Sat Nav (excl.functionality)				
Ice Operates (excl. functionality)				
Central Locking (excl. Key Fob)				
Windows				
Wipers/Washers				
Roof Electrics				
Horn				
Lights				
Indicators				
Dashboard Checks				
Engine Management Light				
ABS Warning Light				
Brake Wear Indicator Light				
Oil Warning Light				
Airbag Waring Light				
nterior Checks	1	I	1	1
2 Keys				
Locking Wheel Nut				
Handbook	Handbook on the centre display			

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 4968

> Make Volvo Date 2024-10-23

Model XC40 Н Service Advisor Registration LV20JFG Tel **MOT Due** M

Chassis No YV1XZ15VDL2341320 Inspected By **Andy Underhill** W Mileage 28829 VHC Type **PDI Check**

	Comments / Recommendations	Net	VAT	Total
G Vehicle has Fuel (20 miles minimum)				
G Tyre Repair Kit				
G Tool Kit				
Documentation		T		I
G V5 Registration Certificate				
G Valid MOT				
G HPI Checked				
G No Outstanding Safety Recalls				
	Total	0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer Size	Comments/Recommendations
G N/S Front	4.0		
G N/S Rear	4.0		
G O/S Front	4.0		
G O/S Rear	4.0		
G Spare			

Photos

Brake Fluid Level - Image 1 of 1



2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1





Customer Signature	The work outlined in this report has been brought to my attention
	-

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.