Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 6107

Make BMW Date 23/07/2025

 H
 Model
 X2
 Service Advisor

 Tel
 M
 Registration
 CF18DDX
 MOT Due

W Chassis No WBAYL12030EK31536 Inspected By Andy Underhill

Mileage 47263 VHC Type PDI Check

	Comments / Recommendations	Net	VAT	Tota
ingine Bay				
Battery State of Health				
Coolant Level				
Power Steering Fluid Level				
Brake Fluid Level				
Washer Bottle Level				
Engine Oil Level				
Oil Contamination				
ingine Running				
Starts				Τ
Engine Running				
Engine Smoking				
Engine Bay Noise				-
Exhaust Condition (no leaks				
& secure)				
ynamic Operations				
Brake Test				
Hand Brake Test				
Static Gear Selection (engine running)				
1st & Reverse Drive Test				
Clutch / Auto Drive take up				
Steering				
Suspension Noise / Ride Height				
Aircon (excl. temp & gassing)				
Sat Nav (excl.functionality)				
Ice Operates (excl. functionality)				
Central Locking (excl. Key Fob)				
Windows				
Wipers/Washers				
Roof Electrics				
Horn				
Lights				
Indicators				
ashboard Checks				
Engine Management Light				
ABS Warning Light				<u> </u>
Brake Wear Indicator Light				
Oil Warning Light				1
Airbag Waring Light				+
nterior Checks			1	1
2 Keys				T
Locking Wheel Nut				+
Handbook				+

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 6107

> Make **BMW** 23/07/2025 Date

Model Х2 Service Advisor Н

Registration CF18DDX MOT Due Tel M

Chassis No Inspected By **Andy Underhill** W WBAYL12030EK31536 Mileage 47263 VHC Type **PDI Check**

	Comments / Recommendations	Net	VAT	Total
G Vehicle has Fuel (20 miles minimum)				
G Tyre Repair Kit	Run flat tyres fitted			
G Tool Kit				
Documentation				
G V5 Registration Certificate				
G Valid MOT				
G HPI Checked				
G No Outstanding Safety Recalls				
'	Total	0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer Size	Comments/Recommendations
G N/S Front	4.0		
G N/S Rear	5.0		
G O/S Front	4.5		
G O/S Rear	5.0		
G Spare			

Photos

Brake Fluid Level - Image 1 of 1




2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Customer Signature	The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.