Steve Clarke Garages Ltd

PDI Check

CUST	OMER DETAIL	VEHICLE DE	TAIL	VHC NO	5576
		Make	Hyundai	Date	12/03/2025
	Н	Model	loniq	Service Advisor	
Tel	Μ	Registration	YL67MSY	MOT Due	
	W	Chassis No	KMHC851CVHU033123	Inspected By	Hristo Klecharov
		Mileage	77211	VHC Type	PDI Check

		Comments / Recommendations	Net	VAT	Total
Ε	ngine Bay				
G	Battery State of Health				
G	Coolant Level				
G	Power Steering Fluid Level				
G	Brake Fluid Level	185°C			
G	Washer Bottle Level				
G	Engine Oil Level				
G	Oil Contamination				
Ε	ngine Running			1	
G	Starts				
G	Engine Running				
G	Engine Smoking				
G	Engine Bay Noise				
G	Exhaust Condition (no leaks & secure)				
D	ynamic Operations		1		
G	Brake Test				
G	Hand Brake Test				
G	Static Gear Selection (engine running)				
G	1st & Reverse Drive Test				
G	Clutch / Auto Drive take up				
G	Steering				
G	Suspension Noise / Ride Height				
G	Aircon (excl. temp & gassing)				
G	Sat Nav (excl.functionality)				
G	Ice Operates (excl. functionality)				
G	Central Locking (excl. Key Fob)				
G	Windows				
G	Wipers/Washers				
Α	Roof Electrics	N/A			
G	Horn				
G	Lights				
G	Indicators				
	ashboard Checks			1	1
G	Engine Management Light				
G	ABS Warning Light				

G	Brake Wear Indicator Light	
G	Oil Warning Light	
G	Airbag Waring Light	

storior Chooko

In	Interior Checks				
G	2 Keys				
G	Locking Wheel Nut				
G	Handbook	Yes			

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL		VEHICLE DETAIL		VHC NO	5576	
		Make	Hyundai	Date	12/03/2025	
	Н	Model	loniq	Service Advisor		
Tel	M	Registration	YL67MSY	MOT Due		
	W	Chassis No	KMHC851CVHU033123	Inspected By	Hristo Klecharov	
		Mileage	77211	VHC Type	PDI Check	


		Comments / Recommendations	Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)	Yes			
Α	Tyre Repair Kit	N/A			
G	Tool Kit				
D	ocumentation				
G	V5 Registration Certificate	Yes			
G	Valid MOT	Yes			
G	HPI Checked	Yes			
G	No Outstanding Safety Recalls				
		Total	0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer Size	Comments/Recommendations
G N/S Front	6.0		
G N/S Rear	7.0		
G O/S Front	6.0		
G O/S Rear	7.0		
G Spare	3.0		

Photos

2 Keys - Image 1 of 1







Tool Kit - Image 1 of 1



Customer Signature

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.