Steve Clarke Garages Ltd

PDI Check

| CUSTOMER DETAIL | | VEHICLE DETAIL | | VHC NO | 5147 | |
|-----------------|---|----------------|-------------------|-----------------|------------------|--|
| | | Make | Toyota | Date | 02/12/2024 | |
| | Н | Model | Yaris | Service Advisor | | |
| Tel | Μ | Registration | LL67ZWH | MOT Due | | |
| | W | Chassis No | VNKKD3D330A408786 | Inspected By | Hristo Klecharov | |
| | | Mileage | 62938 | VHC Type | PDI Check | |
| | | | | | | |

| | | Comments / Recommendations | Net | VAT | Total |
|----|--|----------------------------|-----|-----|-------|
| E | ngine Bay | | | | |
| G | Battery State of Health | | | | |
| G | Coolant Level | | | | |
| G | Power Steering Fluid Level | | | | |
| G | Brake Fluid Level | 200°C | | | |
| G | Washer Bottle Level | | | | |
| G | Engine Oil Level | | | | |
| G | Oil Contamination | | | | |
| E | ngine Running | | | | |
| G | Starts | | | | |
| G | Engine Running | | | | |
| G | Engine Smoking | | | | |
| G | Engine Bay Noise | | | | |
| G | Exhaust Condition (no leaks & secure) | | | | |
| D | ynamic Operations | | | | |
| G | Brake Test | | | | |
| G | Hand Brake Test | | | | |
| G | Static Gear Selection (engine running) | | | | |
| G | 1st & Reverse Drive Test | | | | |
| G | Clutch / Auto Drive take up | | | | |
| G | Steering | | | | |
| G | Suspension Noise / Ride Height | | | | |
| G | Aircon (excl. temp & gassing) | | | | |
| А | Sat Nav (excl.functionality) | N/A | | | |
| G | Ice Operates (excl. functionality) | | | | |
| G | Central Locking (excl. Key Fob) | | | | |
| G | Windows | | | | |
| G | Wipers/Washers | | | | |
| А | Roof Electrics | N/A | | | |
| G | Horn | | | | |
| G | Lights | | | | |
| G | Indicators | | | | |
| D | ashboard Checks | | | | 1 |
| G | Engine Management Light | | | | |
| G | ABS Warning Light | | | | |
| G | Brake Wear Indicator Light | | | | |
| G | Oil Warning Light | | | | |
| G | Airbag Waring Light | | | | |
| In | terior Checks | | 1 | | |

| m | lenor checks | | | |
|---|-------------------|-----|--|--|
| G | 2 Keys | | | |
| G | Locking Wheel Nut | | | |
| G | Handbook | Yes | | |
| | | | | |

Steve Clarke Garages Ltd

PDI Check

| CUST | OMER DETAIL | VEHICLE DETAIL | | VHC NO | 5147 | |
|------|-------------|----------------|-------------------|-----------------|------------------|--|
| | | Make | Toyota | Date | 02/12/2024 | |
| | Н | Model | Yaris | Service Advisor | | |
| Tel | Μ | Registration | LL67ZWH | MOT Due | | |
| | W | Chassis No | VNKKD3D330A408786 | Inspected By | Hristo Klecharov | |
| | | Mileage | 62938 | VHC Туре | PDI Check | |

| | | Comments / Recommendations | Net | VAT | Total |
|----|--|----------------------------|------|------|-------|
| G | Vehicle has Fuel (20 miles minimum) | Yes | | | |
| А | Tyre Repair Kit | N/A | | | |
| G | Tool Kit | | | | |
| Do | ocumentation | | | | |
| G | V5 Registration Certificate | Yes | | | |
| G | Valid MOT | Yes | | | |
| G | HPI Checked | | | | |
| G | No Outstanding Safety Recalls | | | | |
| | | Tota | 0.00 | 0.00 | 0.00 |

| Tyres | Tread (mm) | Manufacturer Size | Comments/Recommendations |
|-------------|------------|-------------------|---------------------------------|
| G N/S Front | 5.0 | | |
| G N/S Rear | 6.0 | | |
| G O/S Front | 4.0 | | |
| G O/S Rear | 6.0 | | |
| G Spare | 3.0 | | |

Photos

2 Keys - Image 1 of 1
Locking Wheel Nut - Image 1 of 1
Tool Kit - Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1

Customer Signature

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.