# **Steve Clarke Garages Ltd**

### **Vehicle Health Check**

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 1616

Make Kia Date 05/02/2021

 H
 Model
 Venga
 Service Advisor

 Tel
 M
 Registration
 AK67HVT
 MOT Due

W Chassis No U5YEH812LJL181519 Inspected By Charlie Wardale

Mileage 19608

	Comments / Recommendations	Net	VAT	Total
Engine Bay				
G Battery State of Health				
G Coolant Level				
G Power Steering Fluid Level				
G Brake Fluid Level	218 degrees			
G Washer Bottle Level				
G Engine Oil Level				
G Oil Contamination				
<b>Engine Running</b>				
G Starts				
G Engine Running				
G Engine Smoking				
G Engine Bay Noise				
G Exhaust Condition (no leaks & secure)				
Dynamic Operations	<u> </u>			
G Brake Test	,			<u> </u>
G Hand Brake Test				
G Static Gear Selection				
(engine running)				
G 1st & Reverse Drive Test				
G Clutch / Auto Drive take up				
G Steering				
G Suspension Noise / Ride Height				
G Aircon (excl. temp & gassing	g)			
G Sat Nav (excl.functionality)				
G Ice Operates (excl. functionality)				
G Central Locking (excl. Key Fob)				
G Windows				
G Wipers/Washers				
G Roof Electrics				
Dashboard Checks				
G Engine Management Light				
G ABS Warning Light				
G Brake Wear Indicator Light				
G Oil Warning Light				
G Airbag Waring Light				
Interior Checks				
G 2 Keys				
G Locking Wheel Nut				
G Handbook				
G Vehicle has Fuel (20 miles minimum)				
A Tyre Repair Kit	N/a			
G Tool Kit			1	1

## **Steve Clarke Garages Ltd**

#### **Vehicle Health Check**

**CUSTOMER DETAIL** VEHICLE DETAIL VHC NO 1616

> Make Kia Date 05/02/2021

Model Н Venga Service Advisor Registration AK67HVT Tel **MOT Due** 

U5YEH812LJL181519 Chassis No Inspected By **Charlie Wardale** W

> 19608 Mileage

		Comments / Recommendations	Net	VAT	Total
D	ocumentation				
G	V5 Registration Certificate				
G	Valid MOT	26/10/21			
G	HPI Checked				
G	No Outstanding Safety Recalls				
		Tota	0.00	0.00	0.00

Tyres Tread (mm)		Manufacturer Size	Comments/Recommendations	
G N/S Front	5.0			
G N/S Rear	5.0			
G O/S Front	5.0			
G O/S Rear	6.0			
G Spare	7.0			

#### **Photos**

M

2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1





Vehicle has Fuel (20 miles minimum) -



Tool Kit - Image 1 of 1



V5 Registration Certificate - Image 1 of 1



#### Customer Signature\_

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.