Steve Clarke Garages Ltd

PDI Check

CUST	OMER DETAIL	VEHICLE DI	ETAIL	VHC NO	4644
		Make	Toyota	Date	2024-08-10
	Н	Model	AYGO	Service Advisor	
Tel	Μ	Registration	WH68NPU	MOT Due	
	W	Chassis No	JTDKGNEC00N417366	Inspected By	Hristo Klecharov
		Mileage	57809	VHC Type	PDI Check

		Comments / Recommendations	Net	VAT	Total
E	ngine Bay				
G	Battery State of Health				
G	Coolant Level				
G	Power Steering Fluid Level				
G	Brake Fluid Level	195°C			
G	Washer Bottle Level				
G	Engine Oil Level				
G	Oil Contamination				
E	ngine Running				-
G	Starts				
G	Engine Running				
G	Engine Smoking				
G	Engine Bay Noise				
G	Exhaust Condition (no leaks & secure)				
D	ynamic Operations				1
G	Brake Test				
G	Hand Brake Test				
G	Static Gear Selection (engine running)				
G	1st & Reverse Drive Test				
G	Clutch / Auto Drive take up				
G	Steering				
G	Suspension Noise / Ride Height				
G	Aircon (excl. temp & gassing)				
А	Sat Nav (excl.functionality)	N/A			
G	Ice Operates (excl. functionality)				
G	Central Locking (excl. Key				
G	Fob)				
G	Windows Wipers/Washers				
A	Roof Electrics	N/A			
G	Horn				
G	Lights				
G	Indicators				
	ashboard Checks		1	1	
G	Engine Management Light				
G	ABS Warning Light				
G	Brake Wear Indicator Light				
G	Oil Warning Light				
G	Airbag Waring Light				
	terior Checks	1	1		[
G	2 Kovs		1	1	1

G	2 Keys			
А	Locking Wheel Nut	N/A		
А	Handbook	N/A		

Steve Clarke Garages Ltd

PDI Check

CUST	OMER DETAIL	VEHICLE DE	TAIL	VHC NO	4644
		Make	Toyota	Date	2024-08-10
	Н	Model	AYGO	Service Advisor	
Tel	М	Registration	WH68NPU	MOT Due	
	W	Chassis No	JTDKGNEC00N417366	Inspected By	Hristo Klecharov
		Mileage	57809	VHC Type	PDI Check

		Comments / Recommendations	Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)	Yes			
А	Tyre Repair Kit	N/A			
G	Tool Kit				
D	ocumentation				
G	V5 Registration Certificate	Yes			
G	Valid MOT	Yes			
G	HPI Checked				
G	No Outstanding Safety				
	Recalls				
		Total	0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer Size	Comments/Recommendations
G N/S Front	3.0		
G N/S Rear	4.0		
G O/S Front	5.0		
G O/S Rear	5.0		
G Spare	3.0		

Photos

2 Keys - Image 1 of 1



Tool Kit - Image 1 of 1



Customer Signature_

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.