Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL

H

Tel M

W

VEHICLE DETAIL

Make **Skoda**
Model **Citigo**
Registration **DE15JHU**
Chassis No **TMBZZZAAZFD621421**
Mileage **13105**

VHC NO **1263**
Date **04/01/2020**
Service Advisor
MOT Due
Inspected By **Hristo Klecharov**

		Comments / Recommendations	Net	VAT	Total
Engine Bay					
G	Battery State of Health				
G	Coolant Level				
G	Power Steering Fluid Level				
G	Brake Fluid Level				
G	Washer Bottle Level				
G	Engine Oil Level				
G	Oil Contamination				
Engine Running					
G	Starts				
G	Engine Running				
G	Engine Smoking				
G	Engine Bay Noise				
G	Exhaust Condition (no leaks & secure)				
Dynamic Operations					
G	Brake Test	222 oC			
G	Hand Brake Test				
G	Static Gear Selection (engine running)				
G	1st & Reverse Drive Test				
G	Clutch / Auto Drive take up				
G	Steering				
G	Suspension Noise / Ride Height				
G	Aircon (excl. temp & gassing)				
G	Sat Nav (excl.functionality)				
G	Ice Operates (excl. functionality)				
G	Central Locking (excl. Key Fob)				
G	Windows				
G	Wipers/Washers				
A	Roof Electrics	N/A			
Dashboard Checks					
G	Engine Management Light				
G	ABS Warning Light				
G	Brake Wear Indicator Light				
G	Oil Warning Light				
G	Airbag Waring Light				
Interior Checks					
G	2 Keys				
G	Locking Wheel Nut				
G	Handbook				
G	Vehicle has Fuel (20 miles minimum)				
G	Tyre Repair Kit				
G	Tool Kit				

Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL		VEHICLE DETAIL			
		Make	Skoda	VHC NO	1263
	H	Model	Citigo	Date	04/01/2020
Tel	M	Registration	DE15JHU	Service Advisor	
	W	Chassis No	TMBZZZAAZFD621421	MOT Due	
		Mileage	13105	Inspected By	Hristo Klecharov

	Comments / Recommendations		Net	VAT	Total
Documentation					
G	V5 Registration Certificate				
G	Valid MOT	21/04/2020			
G	HPI Checked				
G	No Outstanding Safety Recalls				
		Total	0.00	0.00	0.00

Tyres		Tread (mm)			Manufacturer	Size	Comments/Recommendations
G	N/S Front		5.0				
G	N/S Rear		6.0				
G	O/S Front		5.0				
G	O/S Rear		6.0				
R	Spare		0.0				

Photos

2 Keys - Image 1 of 1

Locking Wheel Nut - Image 1 of 1

Handbook - Image 1 of 1

Vehicle has Fuel (20 miles minimum) -

Tyre Repair Kit - Image 1 of 1

V5 Registration Certificate - Image 1 of 1

Customer Signature_____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.