

# Steve Clarke Garages Ltd

# Vehicle Health Check

## CUSTOMER DETAIL

## VEHICLE DETAIL

VHC NO

1149

H  
Tel M  
W

Make Nissan  
Model Leaf  
Registration PF16NNY  
Chassis No SJNFAAZE0U6052029  
Mileage 16188

Date 16/09/2019  
Service Advisor  
MOT Due  
Inspected By Spence Hitchcock

Comments / Recommendations		Net	VAT	Total
<b>Engine Bay</b>				
G	Battery State of Health			
G	Coolant Level			
G	Power Steering Fluid Level			
G	Brake Fluid Level			
G	Washer Bottle Level			
A	Engine Oil Level	N/A		
A	Oil Contamination	N/A		
<b>Engine Running</b>				
G	Starts			
G	Engine Running			
A	Engine Smoking	N/A		
G	Engine Bay Noise			
A	Exhaust Condition (no leaks & secure)	N/A		
<b>Dynamic Operations</b>				
G	Brake Test			
G	Hand Brake Test			
G	Static Gear Selection (engine running)			
G	1st & Reverse Drive Test			
G	Clutch / Auto Drive take up			
G	Steering			
G	Suspension Noise / Ride Height			
G	Aircon (excl. temp & gassing)			
G	Sat Nav (excl.functionality)			
G	Ice Operates (excl. functionality)			
G	Central Locking (excl. Key Fob)			
G	Windows			
G	Wipers/Washers			
A	Roof Electrics	N/A		
<b>Dashboard Checks</b>				
G	Engine Management Light			
G	ABS Warning Light			
G	Brake Wear Indicator Light			
A	Oil Warning Light	N/A		
G	Airbag Waring Light			
<b>Interior Checks</b>				
G	2 Keys			
G	Locking Wheel Nut			
G	Handbook			
G	Vehicle has Fuel (20 miles minimum)			
G	Tyre Repair Kit			
G	Tool Kit			

# Steve Clarke Garages Ltd

# Vehicle Health Check

## CUSTOMER DETAIL

## VEHICLE DETAIL

VHC NO

1149

H  
Tel M  
W

Make **Nissan**  
Model **Leaf**  
Registration **PF16NNY**  
Chassis No **SJNFAAZE0U6052029**  
Mileage **16188**

Date **16/09/2019**  
Service Advisor  
MOT Due  
Inspected By **Spence Hitchcock**

Comments / Recommendations		Net	VAT	Total
<b>Documentation</b>				
G	V5 Registration Certificate			
G	Valid MOT	30/06/2020		
G	HPI Checked			
G	No Outstanding Safety Recalls			
<b>Total</b>		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	4.0			
G N/S Rear	7.0			
G O/S Front	6.0			
G O/S Rear	6.0			
R Spare	0.0			

## Photos

2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Vehicle has Fuel (20 miles minimum) -



Tyre Repair Kit - Image 1 of 1



Tool Kit - Image 1 of 1





**Customer Signature** \_\_\_\_\_ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.