Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 1504

Make DS AUTOMOBILES Date 05/09/2020

 H
 Model
 Citroen DS 3
 Service Advisor

 Tel
 M
 Registration
 BJ16XGT
 MOT Due

W Chassis No VF7SABHY6GW523484 Inspected By Charlie Wardale

Mileage 36894

		Comments / Recommendations	Net	VAT	Total
E	ngine Bay				
G	Battery State of Health				
G	Coolant Level				
G	Power Steering Fluid Level				
G	Brake Fluid Level				
G	Washer Bottle Level				
G	Engine Oil Level				
G	Oil Contamination				
E	ngine Running				
G	Starts				
G	Engine Running				
G	Engine Smoking				
G	Engine Bay Noise				
G	Exhaust Condition (no leaks & secure)				
D	ynamic Operations				
G	Brake Test				
G	Hand Brake Test				
G	Static Gear Selection (engine running)				
G	1st & Reverse Drive Test				
G	Clutch / Auto Drive take up				
G	Steering				
G	Suspension Noise / Ride Height				
G	Aircon (excl. temp & gassing)				
Α	Sat Nav (excl.functionality)	N/a			
G	Ice Operates (excl. functionality)				
G	Central Locking (excl. Key Fob)				
G	Windows				
G	Wipers/Washers				
Α	Roof Electrics	N/a			
	ashboard Checks		I		
G	Engine Management Light				
G	ABS Warning Light				
G	Brake Wear Indicator Light				
G	Oil Warning Light				
G	Airbag Waring Light				
	terior Checks		I	<u> </u>	
G G	2 Keys				
G	Locking Wheel Nut Handbook				
G	Vehicle has Fuel (20 miles				
-0	minimum)				
Α	Tyre Repair Kit	N/a			
G	Tool Kit				

Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 1504

> Make **DS AUTOMOBILES** 05/09/2020 Date

Model Citroen DS 3 Н Service Advisor **BJ16XGT** Tel Registration MOT Due M

Chassis No VF7SABHY6GW523484 Inspected By **Charlie Wardale** W

> Mileage 36894

		Comments / Recommendations	Net	VAT	Total		
D	Documentation						
G	V5 Registration Certificate						
G	Valid MOT	11/11/2020					
G	HPI Checked						
G	No Outstanding Safety Recalls						
		Total	0.00	0.00	0.00		

Tyres	Tread (mm)) Manufacturer Size	Comments/Recommendations
G N/S Front	5.0		
G N/S Rear	6.0		
G O/S Front	4.0		
G O/S Rear	5.0		
G Spare	5.0		

Photos

2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Vehicle has Fuel (20 miles minimum) -



Tool Kit - Image 1 of 1



V5 Registration Certificate - Image 1 of 1



Customer Signature

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.