

# Steve Clarke Garages Ltd

# PDI Check

CUSTOMER DETAIL

H

M

W

Tel

VEHICLE DETAIL

Make

Mazda

Model

Mazda3

Registration

DK21KZD

Chassis No

JM4BP6HEA01203682

Mileage

14351

VHC NO

5835

Date

16/05/2025

Service Advisor

MOT Due

Inspected By

Josiah Clarke

VHC Type

PDI Check

Comments / Recommendations			Net	VAT	Total
Engine Bay					
G	Battery State of Health	Good and recharge			
G	Coolant Level				
G	Power Steering Fluid Level				
G	Brake Fluid Level	194°C boiling point			
G	Washer Bottle Level				
G	Engine Oil Level				
G	Oil Contamination				
Engine Running					
G	Starts				
G	Engine Running				
G	Engine Smoking				
G	Engine Bay Noise				
G	Exhaust Condition (no leaks & secure)				
Dynamic Operations					
G	Brake Test				
G	Hand Brake Test				
G	Static Gear Selection (engine running)				
G	1st & Reverse Drive Test				
G	Clutch / Auto Drive take up				
G	Steering				
G	Suspension Noise / Ride Height				
G	Aircon (excl. temp & gassing)				
G	Sat Nav (excl.functionality)				
G	Ice Operates (excl. functionality)				
G	Central Locking (excl. Key Fob)				
G	Windows				
G	Wipers/Washers				
G	Roof Electrics				
G	Horn				
G	Lights				
G	Indicators				
Dashboard Checks					
G	Engine Management Light				
G	ABS Warning Light				
G	Brake Wear Indicator Light				
G	Oil Warning Light				
G	Airbag Waring Light				
Interior Checks					
G	2 Keys				
G	Locking Wheel Nut				
G	Handbook				

# Steve Clarke Garages Ltd

# PDI Check

CUSTOMER DETAIL

H  
Tel M  
W

VEHICLE DETAIL

Make Mazda  
Model Mazda3  
Registration DK21KZD  
Chassis No JM4BP6HEA01203682  
Mileage 14351


VHC NO 5835  
Date 16/05/2025  
Service Advisor  
MOT Due  
Inspected By Josiah Clarke  
VHC Type PDI Check

Comments / Recommendations		Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)			
G	Tyre Repair Kit			
G	Tool Kit			
Documentation				
G	V5 Registration Certificate			
G	Valid MOT			
G	HPI Checked			
G	No Outstanding Safety Recalls			
Total		0.00	0.00	0.00

Tyres	Tread (mm)			Manufacturer	Size	Comments/Recommendations
G N/S Front		6.3				
G N/S Rear		6.5				
G O/S Front		6.7				
G O/S Rear		6.7				
G Spare						

Photos


2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1




Handbook - Image 1 of 1



Vehicle has Fuel (20 miles minimum) - Image 1 of 1



Tyre Repair Kit - Image 1 of 1



**Customer Signature**\_\_\_\_\_ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.