

# Steve Clarke Garages Ltd

# Vehicle Health Check

CUSTOMER DETAIL

H

Tel

M

W

VEHICLE DETAIL

Make

Renault

Model

Captur

Registration

HT16RVL

Chassis No

VF12RAR1C55508176

Mileage

19680

VHC NO

1014

Date

26/07/2019

Service Advisor

MOT Due

Inspected By

Sophie Carpenter

| Comments / Recommendations |  | Net | VAT | Total |
|----------------------------|--|-----|-----|-------|
| Engine Bay                 |  |     |     |       |
| G                          | Battery State of Health                |     |     |       |
| G                          | Coolant Level                          |     |     |       |
| G                          | Power Steering Fluid Level             |     |     |       |
| G                          | Brake Fluid Level                      |     |     |       |
| G                          | Washer Bottle Level                    |     |     |       |
| G                          | Engine Oil Level                       |     |     |       |
| G                          | Oil Contamination                      |     |     |       |
| Engine Running             |  |     |     |       |
| G                          | Starts                                 |     |     |       |
| G                          | Engine Running                         |     |     |       |
| G                          | Engine Smoking                         |     |     |       |
| G                          | Engine Bay Noise                       |     |     |       |
| G                          | Exhaust Condition (no leaks & secure)  |     |     |       |
| Dynamic Operations         |  |     |     |       |
| G                          | Brake Test                             |     |     |       |
| G                          | Hand Brake Test                        |     |     |       |
| G                          | Static Gear Selection (engine running) |     |     |       |
| G                          | 1st & Reverse Drive Test               |     |     |       |
| G                          | Clutch / Auto Drive take up            |     |     |       |
| G                          | Steering                               |     |     |       |
| G                          | Suspension Noise / Ride Height         |     |     |       |
| G                          | Aircon (excl. temp & gassing)          |     |     |       |
| G                          | Sat Nav (excl.functionality)           |     |     |       |
| G                          | Ice Operates (excl. functionality)     |     |     |       |
| G                          | Central Locking (excl. Key Fob)        |     |     |       |
| G                          | Windows                                |     |     |       |
| G                          | Wipers/Washers                         |     |     |       |
| A                          | Roof Electrics                         | N/a |     |       |
| Dashboard Checks           |  |     |     |       |
| G                          | Engine Management Light                |     |     |       |
| G                          | ABS Warning Light                      |     |     |       |
| G                          | Brake Wear Indicator Light             |     |     |       |
| G                          | Oil Warning Light                      |     |     |       |
| G                          | Airbag Waring Light                    |     |     |       |
| Interior Checks            |  |     |     |       |
| G                          | 2 Keys                                 |     |     |       |
| G                          | Locking Wheel Nut                      |     |     |       |
| G                          | Handbook                               |     |     |       |
| G                          | Vehicle has Fuel (20 miles minimum)    |     |     |       |
| A                          | Tyre Repair Kit                        | N/a |     |       |
| G                          | Tool Kit                               |     |     |       |

# Steve Clarke Garages Ltd

# Vehicle Health Check

## CUSTOMER DETAIL

## VEHICLE DETAIL

VHC NO

1014

H  
Tel M  
W

Make Renault  
Model Captur  
Registration HT16RVL  
Chassis No VF12RAR1C55508176  
Mileage 19680

Date 26/07/2019  
Service Advisor  
MOT Due  
Inspected By Sophie Carpenter

| Comments / Recommendations |                               | Net        | VAT  | Total |
|----------------------------|-------------------------------|------------|------|-------|
| <b>Documentation</b>       |                               |            |      |       |
| G                          | V5 Registration Certificate   |            |      |       |
| G                          | Valid MOT                     | 08/07/2020 |      |       |
| G                          | HPI Checked                   |            |      |       |
| G                          | No Outstanding Safety Recalls |            |      |       |
| <b>Total</b>               |                               | 0.00       | 0.00 | 0.00  |

| Tyres       | Tread (mm) | Manufacturer | Size | Comments/Recommendations |
|-------------|------------|--------------|------|--------------------------|
| G N/S Front | 4.0        |              |      |                          |
| G N/S Rear  | 5.0        |              |      |                          |
| G O/S Front | 6.0        |              |      |                          |
| G O/S Rear  | 5.0        |              |      |                          |
| G Spare     | 4.0        |              |      |                          |

## Photos

2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Vehicle has Fuel (20 miles minimum) -



Tool Kit - Image 1 of 1



V5 Registration Certificate - Image 1 of 1



**Customer Signature**

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.