

Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL

H
Tel M
W

VEHICLE DETAIL

Make **Ford**
Model **EcoSport**
Registration **WH19LNA**
Chassis No **WF01XXERK1KC79219**
Mileage **21547**

VHC NO **2048**

Date **16/03/2022**

Service Advisor

MOT Due

Inspected By **Charlie Wardale**

Comments / Recommendations		Net	VAT	Total
Engine Bay				
G	Battery State of Health			
G	Coolant Level			
G	Power Steering Fluid Level			
G	Brake Fluid Level			
G	Washer Bottle Level			
G	Engine Oil Level			
G	Oil Contamination			
Engine Running				
G	Starts			
G	Engine Running			
G	Engine Smoking			
G	Engine Bay Noise			
G	Exhaust Condition (no leaks & secure)			
Dynamic Operations				
G	Brake Test			
G	Hand Brake Test			
G	Static Gear Selection (engine running)			
G	1st & Reverse Drive Test			
G	Clutch / Auto Drive take up			
G	Steering			
G	Suspension Noise / Ride Height			
G	Aircon (excl. temp & gassing)			
G	Sat Nav (excl. functionality)			
G	Ice Operates (excl. functionality)			
G	Central Locking (excl. Key Fob)			
G	Windows			
G	Wipers/Washers			
A	Roof Electrics	N/a		
G	Horn			
G	Lights			
G	Indicators			
Dashboard Checks				
G	Engine Management Light			
G	ABS Warning Light			
G	Brake Wear Indicator Light			
G	Oil Warning Light			
G	Airbag Warning Light			
Interior Checks				
G	2 Keys			
G	Locking Wheel Nut			
G	Handbook			
G	Vehicle has Fuel (20 miles minimum)			

Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL

VEHICLE DETAIL

VHC NO 2048

H
Tel M
W

Make **Ford**
Model **EcoSport**
Registration **WH19LNA**
Chassis No **WF01XXERK1KC79219**
Mileage **21547**

Date **16/03/2022**
Service Advisor
MOT Due
Inspected By **Charlie Wardale**

Comments / Recommendations		Net	VAT	Total
G	Tyre Repair Kit			
A	Tool Kit	N/a		
Documentation				
G	V5 Registration Certificate			
G	Valid MOT	20/07/22		
G	HPI Checked			
G	No Outstanding Safety Recalls			
Total		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	7.0			
G N/S Rear	5.0			
G O/S Front	6.0			
G O/S Rear	5.0			
G Spare				

Photos


2 Keys - Image 1 of 1




Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Vehicle has Fuel (20 miles minimum) -



Tyre Repair Kit - Image 1 of 1



V5 Registration Certificate - Image 1 of 1



Customer Signature _____

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.