

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL

Mr Paul Hampshire
 H
 Tel M 07714341547
 W 07771851532 Mr

VEHICLE DETAIL

Make BMW
 Model 2 Series Active Tourer
 Registration P40LPH
 Chassis No WBA6Y320X07F64019
 Mileage 22105

VHC NO

7313

Date 14/05/2026
 Service Advisor
 MOT Due 21/02/2027
 Inspected By Hristo Klecharov
 VHC Type PDI Check

Comments / Recommendations		Net	VAT	Total
Engine Bay				
G	Battery State of Health			
G	Coolant Level			
G	Power Steering Fluid Level			
G	Brake Fluid Level	230°C fresh fluid		
G	Washer Bottle Level			
G	Engine Oil Level			
G	Oil Contamination			
Engine Running				
G	Starts			
G	Engine Running			
G	Engine Smoking			
G	Engine Bay Noise			
G	Exhaust Condition (no leaks & secure)			
Dynamic Operations				
G	Brake Test			
G	Hand Brake Test			
G	Static Gear Selection (engine running)			
G	1st & Reverse Drive Test			
G	Clutch / Auto Drive take up			
G	Steering			
G	Suspension Noise / Ride Height			
G	Aircon (excl. temp & gassing)			
G	Sat Nav (excl. functionality)			
G	Ice Operates (excl. functionality)			
G	Central Locking (excl. Key Fob)			
G	Windows			
G	Wipers/Washers			
A	Roof Electrics	N/a		
G	Horn			
G	Lights			
G	Indicators			
Dashboard Checks				
G	Engine Management Light			
G	ABS Warning Light			
G	Brake Wear Indicator Light			
G	Oil Warning Light			
G	Airbag Warning Light			
Interior Checks				
G	2 Keys			
G	Locking Wheel Nut			
G	Handbook	Yes		

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL

Mr Paul Hampshire
 H
 Tel M 07714341547
 W 07771851532 Mr

VEHICLE DETAIL

Make BMW
 Model 2 Series Active Tourer
 Registration P40LPH
 Chassis No WBA6Y320X07F64019
 Mileage 22105

VHC NO 7313


Date 14/05/2026
 Service Advisor
 MOT Due 21/02/2027
 Inspected By Hristo Klecharov
 VHC Type PDI Check

Comments / Recommendations		Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)	Yes		
A	Tyre Repair Kit	Run flat tires		
G	Tool Kit	Charging cables		
Documentation				
G	V5 Registration Certificate	Yes		
G	Valid MOT	Yes		
G	HPI Checked	Yes		
G	No Outstanding Safety Recalls			
Total		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	4.0			
G N/S Rear	4.0			
G O/S Front	4.0			
G O/S Rear	4.0			
R Spare	0.0			

Photos

2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Tool Kit - Image 1 of 1



Customer Signature _____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 90 days from inspection.