Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL		VEHICLE DETAIL			
				VHC NO	8110
		Make	Toyota	Date	23/09/2026
	H	Model	Yaris	Service Advisor	
Tel	M	Registration	WD17VKO	MOT Due	
	W	Chassis No	VNKKG3D3X0A010448	Inspected By	Hristo Klecharov
		Mileage	74948	VHC Type	PDI Check

		Comments / Recommendations	Net	VAT	Total
Engine Bay					
G	Battery State of Health				
G	Coolant Level				
G	Power Steering Fluid Level				
G	Brake Fluid Level	210°C			
G	Washer Bottle Level				
G	Engine Oil Level				
G	Oil Contamination				
Engine Running					
G	Starts				
G	Engine Running				
G	Engine Smoking				
G	Engine Bay Noise				
G	Exhaust Condition (no leaks & secure)				
Dynamic Operations					
G	Brake Test				
G	Hand Brake Test				
G	Static Gear Selection (engine running)				
G	1st & Reverse Drive Test				
G	Clutch / Auto Drive take up				
G	Steering				
G	Suspension Noise / Ride Height				
G	Aircon (excl. temp & gassing)				
A	Sat Nav (excl.functionality)	N/A			
G	Ice Operates (excl. functionality)				
G	Central Locking (excl. Key Fob)				
G	Windows				
G	Wipers/Washers				
A	Roof Electrics	N/A			
G	Horn				
G	Lights				
G	Indicators				
Dashboard Checks					
G	Engine Management Light				
G	ABS Warning Light				
G	Brake Wear Indicator Light				
G	Oil Warning Light				
G	Airbag Waring Light				
Interior Checks					
G	2 Keys				
G	Locking Wheel Nut				
G	Handbook	Yes			

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL		VEHICLE DETAIL			
		Make	Toyota	VHC NO	8110
	H	Model	Yaris	Date	23/09/2026
Tel	M	Registration	WD17VKO	Service Advisor	
	W	Chassis No	VNKKG3D3X0A010448	MOT Due	
		Mileage	74948	Inspected By	Hristo Klecharov
				VHC Type	PDI Check

	Comments / Recommendations		Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)	Yes			
A	Tyre Repair Kit	N/A			
G	Tool Kit				
Documentation					
G	V5 Registration Certificate	Yes			
G	Valid MOT	Yes			
G	HPI Checked	Yes			
G	No Outstanding Safety Recalls				
		Total	0.00	0.00	0.00

Tyres		Tread (mm)			Manufacturer	Size	Comments/Recommendations
G	N/S Front		6.0				
G	N/S Rear		5.0				
G	O/S Front		6.0				
G	O/S Rear		5.0				
G	Spare		3.0				

Photos

2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1

Tool Kit - Image 1 of 1



Customer Signature_____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 90 days from inspection.