

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL

INTERNAL
H
Tel M
W

VEHICLE DETAIL

Make Ford
Model Fiesta
Registration AY12WWV
Chassis No WF0JXXGAJJCR75025
Mileage 44992

VHC NO 5712
Date 10/04/2025
Service Advisor
MOT Due 03/07/2025
Inspected By Andy Underhill
VHC Type PDI Check

Comments / Recommendations		Net	VAT	Total
Engine Bay				
G	Battery State of Health			
G	Coolant Level			
G	Power Steering Fluid Level			
G	Brake Fluid Level			
G	Washer Bottle Level			
G	Engine Oil Level			
G	Oil Contamination			
Engine Running				
G	Starts			
G	Engine Running			
G	Engine Smoking			
G	Engine Bay Noise			
G	Exhaust Condition (no leaks & secure)			
Dynamic Operations				
G	Brake Test			
G	Hand Brake Test			
G	Static Gear Selection (engine running)			
G	1st & Reverse Drive Test			
G	Clutch / Auto Drive take up			
G	Steering			
G	Suspension Noise / Ride Height			
G	Aircon (excl. temp & gassing)			
G	Sat Nav (excl. functionality)			
G	Ice Operates (excl. functionality)			
G	Central Locking (excl. Key Fob)			
G	Windows			
G	Wipers/Washers			
G	Roof Electrics			
G	Horn			
G	Lights			
G	Indicators			
Dashboard Checks				
G	Engine Management Light			
G	ABS Warning Light			
G	Brake Wear Indicator Light			
G	Oil Warning Light			
G	Airbag Warning Light			
Interior Checks				
A	2 Keys	Only 1 key present		
G	Locking Wheel Nut			
A	Handbook	No handbook present		

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL

INTERNAL
H
Tel M
W

VEHICLE DETAIL

Make **Ford**
Model **Fiesta**
Registration **AY12WWV**
Chassis No **WF0JXXGAJJCR75025**
Mileage **44992**

VHC NO **5712**

Date **10/04/2025**
Service Advisor
MOT Due **03/07/2025**
Inspected By **Andy Underhill**
VHC Type **PDI Check**

Comments / Recommendations		Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)			
G	Tyre Repair Kit			
G	Tool Kit			
Documentation				
G	V5 Registration Certificate			
G	Valid MOT			
G	HPI Checked			
G	No Outstanding Safety Recalls			
Total		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	7.0			
G N/S Rear	6.0			
G O/S Front	7.0			
G O/S Rear	7.0			
G Spare				

Photos

2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Tyre Repair Kit - Image 1 of 1



Customer Signature _____

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.