

Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL

H
Tel M
W

VEHICLE DETAIL

Make Peugeot
Model 208
Registration KR16RSY
Chassis No VF3CCHMZ6GT084145
Mileage 30167

VHC NO

2036

Date 08/03/2022

Service Advisor

MOT Due

Inspected By Charlie Wardale

| Comments / Recommendations | | Net | VAT | Total |
|----------------------------|--|-------------|-----|-------|
| Engine Bay | | | | |
| G | Battery State of Health | | | |
| G | Coolant Level | | | |
| G | Power Steering Fluid Level | | | |
| G | Brake Fluid Level | 204 degrees | | |
| G | Washer Bottle Level | | | |
| G | Engine Oil Level | | | |
| G | Oil Contamination | | | |
| Engine Running | | | | |
| G | Starts | | | |
| G | Engine Running | | | |
| G | Engine Smoking | | | |
| G | Engine Bay Noise | | | |
| G | Exhaust Condition (no leaks & secure) | | | |
| Dynamic Operations | | | | |
| G | Brake Test | | | |
| G | Hand Brake Test | | | |
| G | Static Gear Selection (engine running) | | | |
| G | 1st & Reverse Drive Test | | | |
| G | Clutch / Auto Drive take up | | | |
| G | Steering | | | |
| G | Suspension Noise / Ride Height | | | |
| G | Aircon (excl. temp & gassing) | | | |
| A | Sat Nav (excl. functionality) | N/a | | |
| G | Ice Operates (excl. functionality) | | | |
| G | Central Locking (excl. Key Fob) | | | |
| G | Windows | | | |
| G | Wipers/Washers | | | |
| A | Roof Electrics | N/a | | |
| G | Horn | | | |
| G | Lights | | | |
| G | Indicators | | | |
| Dashboard Checks | | | | |
| G | Engine Management Light | | | |
| G | ABS Warning Light | | | |
| G | Brake Wear Indicator Light | | | |
| G | Oil Warning Light | | | |
| G | Airbag Warning Light | | | |
| Interior Checks | | | | |
| G | 2 Keys | | | |
| G | Locking Wheel Nut | | | |
| G | Handbook | | | |
| G | Vehicle has Fuel (20 miles minimum) | | | |

Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL

VEHICLE DETAIL

VHC NO 2036

H
Tel M
W

Make Peugeot
Model 208
Registration KR16RSY
Chassis No VF3CCHMZ6GT084145
Mileage 30167


Date 08/03/2022
Service Advisor
MOT Due
Inspected By Charlie Wardale

| Comments / Recommendations | | Net | VAT | Total |
|----------------------------|-------------------------------|----------|------|-------|
| A | Tyre Repair Kit | N/a | | |
| G | Tool Kit | | | |
| Documentation | | | | |
| G | V5 Registration Certificate | | | |
| G | Valid MOT | 02/06/22 | | |
| G | HPI Checked | | | |
| G | No Outstanding Safety Recalls | | | |
| Total | | 0.00 | 0.00 | 0.00 |

| Tyres | Tread (mm) | Manufacturer | Size | Comments/Recommendations |
|-------------|------------|--------------|------|--------------------------|
| G N/S Front | 7.0 | | | |
| G N/S Rear | 5.0 | | | |
| G O/S Front | 8.0 | | | |
| G O/S Rear | 8.0 | | | |
| G Spare | 5.0 | | | |

Photos

2 Keys - Image 1 of 1




Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Vehicle has Fuel (20 miles minimum) -



Tool Kit - Image 1 of 1



V5 Registration Certificate - Image 1 of 1



Customer Signature _____

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.