

CUSTOMER DETAIL

H

M

W

Tel

VEHICLE DETAIL

Make

Hyundai

Model

Santa Fe

Registration

WG66EWZ

Chassis No

KMHSW81XNGU690119

Mileage

42209

VHC NO

2139

Date

06/08/2022

Service Advisor

MOT Due

Inspected By

Andy Underhill

Comments / Recommendations			Net	VAT	Total
Engine Bay					
G	Battery State of Health				
G	Coolant Level				
G	Power Steering Fluid Level				
G	Brake Fluid Level				
G	Washer Bottle Level				
G	Engine Oil Level				
G	Oil Contamination				
Engine Running					
G	Starts				
G	Engine Running				
G	Engine Smoking				
G	Engine Bay Noise				
G	Exhaust Condition (no leaks & secure)				
Dynamic Operations					
G	Brake Test				
G	Hand Brake Test				
G	Static Gear Selection (engine running)				
G	1st & Reverse Drive Test				
G	Clutch / Auto Drive take up				
G	Steering				
G	Suspension Noise / Ride Height				
G	Aircon (excl. temp & gassing)				
G	Sat Nav (excl.functionality)				
G	Ice Operates (excl. functionality)				
G	Central Locking (excl. Key Fob)				
G	Windows				
G	Wipers/Washers				
G	Roof Electrics				
G	Horn				
G	Lights				
G	Indicators				
Dashboard Checks					
G	Engine Management Light				
G	ABS Warning Light				
G	Brake Wear Indicator Light				
G	Oil Warning Light				
G	Airbag Waring Light				
Interior Checks					
G	2 Keys				
G	Locking Wheel Nut				
G	Handbook				
G	Vehicle has Fuel (20 miles minimum)				

CUSTOMER DETAIL

H
M
W

Tel

VEHICLE DETAIL

Make Hyundai
Model Santa Fe
Registration WG66EWZ
Chassis No KMHSW81XNGU690119
Mileage 42209

VHC NO 2139
Date 06/08/2022
Service Advisor
MOT Due
Inspected By Andy Underhill

Comments / Recommendations		Net	VAT	Total
G	Tyre Repair Kit			
G	Tool Kit			
Documentation				
G	V5 Registration Certificate			
G	Valid MOT			
G	HPI Checked			
G	No Outstanding Safety Recalls			
Total		0.00	0.00	0.00

Tyres	Tread (mm)			Manufacturer	Size	Comments/Recommendations
G N/S Front		4.0				
G N/S Rear		4.0				
G O/S Front		4.1				
G O/S Rear		3.4				
G Spare		6.0				

Photos

Brake Fluid Level - Image 1 of 1



2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Tool Kit - Image 1 of 1



V5 Registration Certificate - Image 1 of 1



Customer Signature _____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.