

CUSTOMER DETAIL

INTERNAL
H
Tel M
W

VEHICLE DETAIL

Make **Smart**
Model **forfour**
Registration **YE66LGZ**
Chassis No **WME4530422Y100480**
Mileage **51526**

VHC NO **4256**
Date **2024-05-07**
Service Advisor
MOT Due **30/10/2024**
Inspected By **Andy Underhill**
VHC Type **PDI Check**

Comments / Recommendations		Net	VAT	Total
Engine Bay				
G	Battery State of Health			
G	Coolant Level			
G	Power Steering Fluid Level			
G	Brake Fluid Level			
G	Washer Bottle Level			
G	Engine Oil Level			
G	Oil Contamination			
Engine Running				
G	Starts			
G	Engine Running			
G	Engine Smoking			
G	Engine Bay Noise			
G	Exhaust Condition (no leaks & secure)			
Dynamic Operations				
G	Brake Test			
G	Hand Brake Test			
G	Static Gear Selection (engine running)			
G	1st & Reverse Drive Test			
G	Clutch / Auto Drive take up			
G	Steering			
G	Suspension Noise / Ride Height			
G	Aircon (excl. temp & gassing)			
G	Sat Nav (excl.functionality)			
G	Ice Operates (excl. functionality)			
G	Central Locking (excl. Key Fob)			
G	Windows			
G	Wipers/Washers			
G	Roof Electrics			
G	Horn			
G	Lights			
G	Indicators			
Dashboard Checks				
G	Engine Management Light			
G	ABS Warning Light			
G	Brake Wear Indicator Light			
G	Oil Warning Light			
G	Airbag Waring Light			
Interior Checks				
G	2 Keys			
G	Locking Wheel Nut			
G	Handbook			

CUSTOMER DETAIL

INTERNAL
H
Tel M
W

VEHICLE DETAIL

Make **Smart**
Model **forfour**
Registration **YE66LGZ**
Chassis No **WME4530422Y100480**
Mileage **51526**

VHC NO **4256**
Date **2024-05-07**
Service Advisor
MOT Due **30/10/2024**
Inspected By **Andy Underhill**
VHC Type **PDI Check**

Comments / Recommendations		Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)			
G	Tyre Repair Kit			
G	Tool Kit			
Documentation				
G	V5 Registration Certificate			
G	Valid MOT			
G	HPI Checked			
G	No Outstanding Safety Recalls			
Total		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	6.0			
G N/S Rear	7.0			
G O/S Front	7.0			
G O/S Rear	6.0			
G Spare				

Photos

Brake Fluid Level - Image 1 of 1



2 Keys - Image 1 of 2



2 Keys - Image 2 of 2



Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Tyre Repair Kit - Image 1 of 1



Customer Signature _____

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.