Steve Clarke Garages Ltd

PDI Check

CUST	OMER DETAIL	VEHICLE DE	TAIL	VHC NO	5229
INTER	NAL	Make	Mercedes-Benz	Date	16/12/2024
	Н	Model	E Class	Service Advisor	
Tel	M	Registration	KO67EFD	MOT Due	12/12/2024
	W	Chassis No	WDD2132332A418782	Inspected By	Hristo Klecharov
		Mileage	82756	VHC Туре	PDI Check

		Comments / Recommendations	Net	VAT	Total
E	ngine Bay				
G	Battery State of Health				
G	Coolant Level				
G	Power Steering Fluid Level				
G	Brake Fluid Level	191°C			
G	Washer Bottle Level				
G	Engine Oil Level				
G	Oil Contamination				
E	ngine Running				
G	Starts				
G	Engine Running				
G	Engine Smoking				
G	Engine Bay Noise				
G	Exhaust Condition (no leaks & secure)				
D	ynamic Operations		1		
G	Brake Test				
G	Hand Brake Test				
G	Static Gear Selection (engine running)				
G	1st & Reverse Drive Test				
G	Clutch / Auto Drive take up				
G	Steering				
G	Suspension Noise / Ride Height				
G	Aircon (excl. temp & gassing)				
G	Sat Nav (excl.functionality)				
G	Ice Operates (excl. functionality)				
G	Central Locking (excl. Key Fob)				
G	Windows				
G	Wipers/Washers				
G	Roof Electrics				
G	Horn				
G G	Lights				
	Indicators				
	ashboard Checks		1		
G	Engine Management Light				
G	ABS Warning Light				
G	Brake Wear Indicator Light				
G G	Oil Warning Light				
	Airbag Waring Light				
			1		
G	2 Keys				
G G	Locking Wheel Nut Handbook	Yoo.			
0	HAHUDUUK	Yes			

Steve Clarke Garages Ltd

PDI Check

CUST	OMER DETAIL	VEHICLE DE	TAIL	VHC NO	5229
INTER	NAL	Make	Mercedes-Benz	Date	16/12/2024
	Н	Model	E Class	Service Advisor	
Tel	M	Registration	KO67EFD	MOT Due	12/12/2024
	W	Chassis No	WDD2132332A418782	Inspected By	Hristo Klecharov
		Mileage	82756	VHC Туре	PDI Check

		Comments / Recommendations	Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)	Yes			
G	Tyre Repair Kit				
А	Tool Kit	N/A			
D	ocumentation				
G	V5 Registration Certificate	Yes			
G	Valid MOT	Yes			
G	HPI Checked				
G	No Outstanding Safety				
	Recalls				
		Tot	al 0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer Size	Comments/Recommendations
G N/S Front	7.0		
G N/S Rear	7.0		
G O/S Front	7.0		
G O/S Rear	7.0		
R Spare	0.0		

Photos

2 Keys - Image 1 of 1
Locking Wheel Nut - Image 1 of 1
Tyre Repair Kit - Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1 of 1

Image 1 of 1
Image 1 of 1
Image 1

Image 1 of 1</td

Customer Signature

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.