# Steve Clarke Garages Ltd

# PDI Check

CUSTOMER DETAIL

H

Tel M

W

VEHICLE DETAIL

| | |
|---|---|
| Make | SEAT |
| Model | Ibiza |
| Registration | FMZ2354 |
| Chassis No | VSSZZZKJ7RR193827 |
| Mileage | 24951 |

| | |
|---|---|
| VHC NO | 8090 |
| Date | 22/09/2026 |
| Service Advisor | |
| MOT Due | |
| Inspected By | Hristo Klecharov |
| VHC Type | PDI Check |

| | | Comments / Recommendations | Net | VAT | Total |
|---|---|---|---|---|---|
| **Engine Bay** | | | | | |
| G | Battery State of Health | | | | |
| G | Coolant Level | | | | |
| G | Power Steering Fluid Level | | | | |
| G | Brake Fluid Level | 200°C | | | |
| G | Washer Bottle Level | | | | |
| G | Engine Oil Level | | | | |
| G | Oil Contamination | | | | |
| **Engine Running** | | | | | |
| G | Starts | | | | |
| G | Engine Running | | | | |
| G | Engine Smoking | | | | |
| G | Engine Bay Noise | | | | |
| G | Exhaust Condition (no leaks & secure) | | | | |
| **Dynamic Operations** | | | | | |
| G | Brake Test | | | | |
| G | Hand Brake Test | | | | |
| G | Static Gear Selection (engine running) | | | | |
| G | 1st & Reverse Drive Test | | | | |
| G | Clutch / Auto Drive take up | | | | |
| G | Steering | | | | |
| G | Suspension Noise / Ride Height | | | | |
| G | Aircon (excl. temp & gassing) | | | | |
| G | Sat Nav (excl.functionality) | | | | |
| G | Ice Operates (excl. functionality) | | | | |
| G | Central Locking (excl. Key Fob) | | | | |
| G | Windows | | | | |
| G | Wipers/Washers | | | | |
| A | Roof Electrics | N/A | | | |
| G | Horn | | | | |
| G | Lights | | | | |
| G | Indicators | | | | |
| **Dashboard Checks** | | | | | |
| G | Engine Management Light | | | | |
| G | ABS Warning Light | | | | |
| G | Brake Wear Indicator Light | | | | |
| G | Oil Warning Light | | | | |
| G | Airbag Waring Light | | | | |
| **Interior Checks** | | | | | |
| G | 2 Keys | | | | |
| G | Locking Wheel Nut | N/A | | | |
| G | Handbook | N/A | | | |

# Steve Clarke Garages Ltd

# PDI Check

| CUSTOMER DETAIL | | VEHICLE DETAIL | | | |
|---|---|---|---|---|---|
| | | Make | SEAT | VHC NO | 8090 |
| | H | Model | Ibiza | Date | 22/09/2026 |
| Tel | M | Registration | FMZ2354 | Service Advisor | |
| | W | Chassis No | VSSZZZKJ7RR193827 | MOT Due | |
| | | Mileage | 24951 | Inspected By | Hristo Klecharov |
| | | | | VHC Type | PDI Check |

| | Comments / Recommendations | | Net | VAT | Total |
|---|---|---|---|---|---|
| G | Vehicle has Fuel (20 miles minimum) | Yes | | | |
| G | Tyre Repair Kit | | | | |
| A | Tool Kit | N/A | | | |
| **Documentation** | | | | | |
| G | V5 Registration Certificate | Yes | | | |
| G | Valid MOT | Yes | | | |
| G | HPI Checked | Mfl | | | |
| G | No Outstanding Safety Recalls | | | | |
| | | **Total:** | 0.00 | 0.00 | 0.00 |

| Tyres | | Tread (mm) | | | Manufacturer | Size | Comments/Recommendations |
|---|---|---|---|---|---|---|---|
| G | N/S Front | | 5.0 | | | | |
| G | N/S Rear | | 6.0 | | | | |
| G | O/S Front | | 5.0 | | | | |
| G | O/S Rear | | 5.0 | | | | |
| R | Spare | | 0.0 | | | | |

## Photos

Tyre Repair Kit - Image 1 of 1



**Customer Signature**_____ The work outlined in this report has been brought to my attention.

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 90 days from inspection.