Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 4711

Make Hyundai Date 2024-08-27

 H
 Model
 i10
 Service Advisor

 Tel
 M
 Registration
 NV21XNW
 MOT Due

W Chassis No NLHDN51EYMZ077562 Inspected By Hristo Klecharov

Mileage 22606 VHC Type PDI Check

	Comments / Recommendations	Net	VAT	Total
Engine Bay				
G Battery State of Health				
G Coolant Level				
G Power Steering Fluid Level				
G Brake Fluid Level	202°C			
G Washer Bottle Level				
G Engine Oil Level				
G Oil Contamination				
Engine Running	1			
G Starts				
G Engine Running				
G Engine Smoking				
G Engine Bay Noise				
G Exhaust Condition (no leaks				
& secure)				
Dynamic Operations				
G Brake Test				
G Hand Brake Test				
Static Gear Selection (engine running)				
1st & Reverse Drive Test				
G Clutch / Auto Drive take up				
G Steering				
Suspension Noise / Ride Height				
G Aircon (excl. temp & gassing)				
Sat Nav (excl.functionality)	N/A apple car play etc.			
Ice Operates (excl. functionality)				
Central Locking (excl. Key Fob)				
G Windows				
Wipers/Washers				
Roof Electrics	N/A			
G Horn				
G Lights				
G Indicators				
Dashboard Checks		·		
G Engine Management Light				
G ABS Warning Light				
G Brake Wear Indicator Light				
G Oil Warning Light				
G Airbag Waring Light				
Interior Checks	1		I	
G 2 Keys				
G Locking Wheel Nut				
G Handbook	Yes			

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 4711

> Make Hyundai Date 2024-08-27

Model i10 Н Service Advisor NV21XNW Tel Registration MOT Due M

Chassis No Inspected By Hristo Klecharov W NLHDN51EYMZ077562

> 22606 VHC Type **PDI Check** Mileage

	Comments / Recommendations		Net	VAT	Total
G Vehicle has Fuel (20 miles minimum)	Yes				
G Tyre Repair Kit					
A Tool Kit	N/A				
Documentation					
G V5 Registration Certificate	Yes				
G Valid MOT	Yes				
G HPI Checked					
G No Outstanding Safety Recalls					
	Т	otal	0.00	0.00	0.00

Tyres	Tread (mm) Manufacturer Size		Comments/Recommendations		
G N/S Front	4.0				
G N/S Rear	7.0				
G O/S Front	5.0				
G O/S Rear	6.0				
R Spare	0.0				

Photos

2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Tyre Repair Kit - Image 1 of 1



Customer Signature_

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.