

Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL

VEHICLE DETAIL

VHC NO

798

H
Tel M
W

Make Volkswagen
Model Golf
Registration WJ16YHM
Chassis No WVWZZZAUZGP599989
Mileage 53802

Date 01/06/2019
Service Advisor
MOT Due
Inspected By Sophie Carpenter

Comments / Recommendations		Net	VAT	Total
Engine Bay				
G	Battery State of Health			
G	Coolant Level			
G	Power Steering Fluid Level			
G	Brake Fluid Level			
G	Washer Bottle Level			
G	Engine Oil Level			
G	Oil Contamination			
Engine Running				
G	Starts			
G	Engine Running			
G	Engine Smoking			
G	Engine Bay Noise			
G	Exhaust Condition (no leaks & secure)			
Dynamic Operations				
G	Brake Test			
G	Hand Brake Test			
G	Static Gear Selection (engine running)			
G	1st & Reverse Drive Test			
G	Clutch / Auto Drive take up			
G	Steering			
G	Suspension Noise / Ride Height			
G	Aircon (excl. temp & gassing)			
A	Sat Nav (excl. functionality)	N/a		
G	Ice Operates (excl. functionality)			
G	Central Locking (excl. Key Fob)			
G	Windows			
G	Wipers/Washers			
A	Roof Electrics	N/a		
Dashboard Checks				
G	Engine Management Light			
G	ABS Warning Light			
G	Brake Wear Indicator Light			
G	Oil Warning Light			
G	Airbag Warning Light			
Interior Checks				
G	2 Keys			
G	Locking Wheel Nut			
G	Handbook			
G	Vehicle has Fuel (20 miles minimum)			
G	Tyre Repair Kit			
G	Tool Kit			

Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL

VEHICLE DETAIL

VHC NO

798

H
Tel M
W

Make Volkswagen
Model Golf
Registration WJ16YHM
Chassis No WVWZZZAUZGP599989
Mileage 53802


Date 01/06/2019
Service Advisor
MOT Due
Inspected By Sophie Carpenter

Comments / Recommendations		Net	VAT	Total
Documentation				
G	V5 Registration Certificate			
G	Valid MOT	25/04/20		
G	HPI Checked			
G	No Outstanding Safety Recalls			
Total		0.00	0.00	0.00


Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	6.0			
G N/S Rear	5.0			
G O/S Front	6.0			
G O/S Rear	5.0			
G Spare	3.0			

Photos

Vehicle has Fuel (20 miles minimum) -



2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Customer Signature _____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.