

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL

VEHICLE DETAIL

VHC NO 6654

H
Tel M
W

Make SEAT
Model Leon
Registration SA64HBD
Chassis No VSSZZZ5FZFR041099
Mileage 74937

Date 06/12/2025
Service Advisor
MOT Due
Inspected By Hristo Klecharov
VHC Type PDI Check

Comments / Recommendations		Net	VAT	Total
Engine Bay				
G	Battery State of Health			
G	Coolant Level			
G	Power Steering Fluid Level			
G	Brake Fluid Level	192°C		
G	Washer Bottle Level			
G	Engine Oil Level			
G	Oil Contamination			
Engine Running				
G	Starts			
G	Engine Running			
G	Engine Smoking			
G	Engine Bay Noise			
G	Exhaust Condition (no leaks & secure)			
Dynamic Operations				
G	Brake Test			
G	Hand Brake Test			
G	Static Gear Selection (engine running)			
G	1st & Reverse Drive Test			
G	Clutch / Auto Drive take up			
G	Steering			
G	Suspension Noise / Ride Height			
G	Aircon (excl. temp & gassing)			
G	Sat Nav (excl. functionality)			
G	Ice Operates (excl. functionality)			
G	Central Locking (excl. Key Fob)			
A	Windows	N/a/f in op from drivers side		
G	Wipers/Washers			
G	Roof Electrics			
G	Horn			
G	Lights			
G	Indicators			
Dashboard Checks				
G	Engine Management Light			
G	ABS Warning Light			
G	Brake Wear Indicator Light			
G	Oil Warning Light			
G	Airbag Warning Light			
Interior Checks				
A	2 Keys	X1 present		
G	Locking Wheel Nut			
G	Handbook	Yes		

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL

VEHICLE DETAIL

VHC NO 6654

H
Tel M
W

Make SEAT
Model Leon
Registration SA64HBD
Chassis No VSSZZZ5FZFR041099
Mileage 74937

Date 06/12/2025
Service Advisor
MOT Due
Inspected By Hristo Klecharov
VHC Type PDI Check

Comments / Recommendations		Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)	Yes		
G	Tyre Repair Kit			
A	Tool Kit	N/A		
Documentation				
G	V5 Registration Certificate	Yes		
G	Valid MOT	Yes		
G	HPI Checked	Yes		
G	No Outstanding Safety Recalls			
Total		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	5.0			
G N/S Rear	4.0			
G O/S Front	5.0			
G O/S Rear	3.0			
R Spare	0.0			

Photos

2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Tyre Repair Kit - Image 1 of 1



Customer Signature _____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 90 days from inspection.