

# Steve Clarke Garages Ltd

# PDI Check

## CUSTOMER DETAIL

INTERNAL  
H  
Tel M  
W

## VEHICLE DETAIL

Make Mercedes-Benz  
Model SL  
Registration HD66ENR  
Chassis No WDD2314662F044691  
Mileage 22263

VHC NO 4651

Date 2024-08-12  
Service Advisor  
MOT Due 21/09/2024  
Inspected By Andy Underhill  
VHC Type PDI Check

Comments / Recommendations		Net	VAT	Total
<b>Engine Bay</b>				
G	Battery State of Health			
G	Coolant Level			
G	Power Steering Fluid Level			
G	Brake Fluid Level			
G	Washer Bottle Level			
G	Engine Oil Level			
G	Oil Contamination			
<b>Engine Running</b>				
G	Starts			
G	Engine Running			
G	Engine Smoking			
G	Engine Bay Noise			
G	Exhaust Condition (no leaks & secure)			
<b>Dynamic Operations</b>				
G	Brake Test			
G	Hand Brake Test			
G	Static Gear Selection (engine running)			
G	1st & Reverse Drive Test			
G	Clutch / Auto Drive take up			
G	Steering			
G	Suspension Noise / Ride Height			
G	Aircon (excl. temp & gassing)			
G	Sat Nav (excl.functionality)			
G	Ice Operates (excl. functionality)			
G	Central Locking (excl. Key Fob)			
G	Windows			
G	Wipers/Washers			
G	Roof Electrics			
G	Horn			
G	Lights			
G	Indicators			
<b>Dashboard Checks</b>				
G	Engine Management Light			
G	ABS Warning Light			
G	Brake Wear Indicator Light			
G	Oil Warning Light			
G	Airbag Waring Light			
<b>Interior Checks</b>				
G	2 Keys			
G	Locking Wheel Nut			
G	Handbook			

# Steve Clarke Garages Ltd

# PDI Check

## CUSTOMER DETAIL

INTERNAL  
H  
Tel M  
W

## VEHICLE DETAIL

Make Mercedes-Benz  
Model SL  
Registration HD66ENR  
Chassis No WDD2314662F044691  
Mileage 22263

VHC NO 4651  
Date 2024-08-12  
Service Advisor  
MOT Due 21/09/2024  
Inspected By Andy Underhill  
VHC Type PDI Check

Comments / Recommendations		Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)			
G	Tyre Repair Kit			
G	Tool Kit			
<b>Documentation</b>				
G	V5 Registration Certificate			
G	Valid MOT			
G	HPI Checked			
G	No Outstanding Safety Recalls			
<b>Total</b>		0.00	0.00	0.00

Tyres	Tread (mm)	Manufacturer	Size	Comments/Recommendations
G N/S Front	4.4			
G N/S Rear	4.0			
G O/S Front	4.5			
G O/S Rear	3.7			
G Spare				

## Photos

Brake Fluid Level - Image 1 of 1




2 Keys - Image 1 of 1




Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Tyre Repair Kit - Image 1 of 1



**Customer Signature** \_\_\_\_\_

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.