Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 4143

Make Toyota Date 2024-03-26

 H
 Model
 Yaris
 Service Advisor

 Tel
 M
 Registration
 NV70HTP
 MOT Due

W Chassis No VNKKBAC320A097217 Inspected By Andy Underhill

Mileage 16595 VHC Type PDI Check

	Comments / Recommendations	Net	VAT	Tota
ngine Bay				
Battery State of Health				
Coolant Level				
Power Steering Fluid Level				
Brake Fluid Level				
Washer Bottle Level				
Engine Oil Level				
Oil Contamination				
ngine Running			1	
Starts				
Engine Running				
Engine Smoking				
Engine Bay Noise				
Exhaust Condition (no leaks				
& secure)				
ynamic Operations				
Brake Test				
Hand Brake Test				
Static Gear Selection (engine running)				
1st & Reverse Drive Test				
Clutch / Auto Drive take up				
Steering				
Suspension Noise / Ride Height				
Aircon (excl. temp & gassing)				
Sat Nav (excl.functionality)				
Ice Operates (excl. functionality)				
Central Locking (excl. Key Fob)				
Windows				
Wipers/Washers				
Roof Electrics				
Horn				
Lights				
Indicators				
ashboard Checks				
Engine Management Light				
ABS Warning Light				
Brake Wear Indicator Light				
Oil Warning Light				
Airbag Waring Light				
terior Checks		ı	•	•
2 Keys				
Locking Wheel Nut				
Handbook				

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 4143

> Make Toyota Date 2024-03-26

Model Yaris Н Service Advisor Tel

MOT Due Registration NV70HTP M Chassis No Andy Underhill W VNKKBAC320A097217 Inspected By


> Mileage 16595 VHC Type **PDI Check**

	Comments / Recommendations	Net	VAT	Total
G Vehicle has Fuel (20 miles minimum)				
G Tyre Repair Kit				
G Tool Kit				
Documentation				
G V5 Registration Certificate				
G Valid MOT				
G HPI Checked				
G No Outstanding Safety Recalls				
	Total	0.00	0.00	0.00

Tyres Tread (mm) Manufacturer Size		Manufacturer Size	Comments/Recommendations		
G N/S Front	4.0				
G N/S Rear	4.0				
G O/S Front	4.0				
G O/S Rear	4.0				
A Spare	2.0				

Photos

Brake Fluid Level - Image 1 of 1




2 Keys - Image 1 of 1




Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1





Customer Signature_____

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.