

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL

H

M

W

Tel

VEHICLE DETAIL

Make

Ford

Model

Focus

Registration

YF72EPA

Chassis No

WF0PXXGCHPNA24480

Mileage

8605

VHC NO

7558

Date

26/06/2026

Service Advisor

MOT Due

Inspected By

Hristo Klecharov

VHC Type

PDI Check

Comments / Recommendations		Net	VAT	Total
Engine Bay				
G	Battery State of Health			
G	Coolant Level			
G	Power Steering Fluid Level			
G	Brake Fluid Level	202°C		
G	Washer Bottle Level			
G	Engine Oil Level			
G	Oil Contamination			
Engine Running				
G	Starts			
G	Engine Running			
G	Engine Smoking			
G	Engine Bay Noise			
G	Exhaust Condition (no leaks & secure)			
Dynamic Operations				
G	Brake Test			
G	Hand Brake Test			
G	Static Gear Selection (engine running)			
G	1st & Reverse Drive Test			
G	Clutch / Auto Drive take up			
G	Steering			
G	Suspension Noise / Ride Height			
G	Aircon (excl. temp & gassing)			
G	Sat Nav (excl.functionality)			
G	Ice Operates (excl. functionality)			
G	Central Locking (excl. Key Fob)			
G	Windows			
G	Wipers/Washers			
A	Roof Electrics	N/A		
G	Horn			
G	Lights			
G	Indicators			
Dashboard Checks				
G	Engine Management Light			
G	ABS Warning Light			
G	Brake Wear Indicator Light			
G	Oil Warning Light			
G	Airbag Waring Light			
Interior Checks				
G	2 Keys			
G	Locking Wheel Nut			
A	Handbook	N/A		

Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL

H
Tel M
W

VEHICLE DETAIL

Make Ford
Model Focus
Registration YF72EPA
Chassis No WF0PXXGCHPNA24480
Mileage 8605

VHC NO 7558
Date 26/06/2026
Service Advisor
MOT Due
Inspected By Hristo Klecharov
VHC Type PDI Check

Comments / Recommendations		Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)	Yes		
A	Tyre Repair Kit	N/A		
G	Tool Kit			
Documentation				
G	V5 Registration Certificate	Yes		
G	Valid MOT	Yes		
G	HPI Checked	Mfl		
G	No Outstanding Safety Recalls			
Total		0.00	0.00	0.00

Tyres	Tread (mm)			Manufacturer	Size	Comments/Recommendations
G N/S Front		5.0				
G N/S Rear		5.0				
G O/S Front		5.0				
G O/S Rear		5.0				
G Spare		3.0				

Photos

2 Keys - Image 1 of 1

Locking Wheel Nut - Image 1 of 1

Tool Kit - Image 1 of 1



Customer Signature _____ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 90 days from inspection.