

CUSTOMER DETAIL

INTERNAL

H  
M  
W

Tel

VEHICLE DETAIL

Make Volkswagen  
Model Golf  
Registration WF19CZW  
Chassis No VVWZZZAUZKP065797  
Mileage 28312

VHC NO 5924

Date 09/06/2025  
Service Advisor  
MOT Due 20/03/2026  
Inspected By Andy Underhill  
VHC Type PDI Check

| Comments / Recommendations |  | Net       | VAT | Total |
|----------------------------|--|-----------|-----|-------|
| Engine Bay                 |  |           |     |       |
| G                          | Battery State of Health                |           |     |       |
| G                          | Coolant Level                          |           |     |       |
| G                          | Power Steering Fluid Level             |           |     |       |
| G                          | Brake Fluid Level                      | 251 deg c |     |       |
| G                          | Washer Bottle Level                    |           |     |       |
| G                          | Engine Oil Level                       |           |     |       |
| G                          | Oil Contamination                      |           |     |       |
| Engine Running             |  |           |     |       |
| G                          | Starts                                 |           |     |       |
| G                          | Engine Running                         |           |     |       |
| G                          | Engine Smoking                         |           |     |       |
| G                          | Engine Bay Noise                       |           |     |       |
| G                          | Exhaust Condition (no leaks & secure)  |           |     |       |
| Dynamic Operations         |  |           |     |       |
| G                          | Brake Test                             |           |     |       |
| G                          | Hand Brake Test                        |           |     |       |
| G                          | Static Gear Selection (engine running) |           |     |       |
| G                          | 1st & Reverse Drive Test               |           |     |       |
| G                          | Clutch / Auto Drive take up            |           |     |       |
| G                          | Steering                               |           |     |       |
| G                          | Suspension Noise / Ride Height         |           |     |       |
| G                          | Aircon (excl. temp & gassing)          |           |     |       |
| G                          | Sat Nav (excl.functionality)           |           |     |       |
| G                          | Ice Operates (excl. functionality)     |           |     |       |
| G                          | Central Locking (excl. Key Fob)        |           |     |       |
| G                          | Windows                                |           |     |       |
| G                          | Wipers/Washers                         |           |     |       |
| G                          | Roof Electrics                         |           |     |       |
| G                          | Horn                                   |           |     |       |
| G                          | Lights                                 |           |     |       |
| G                          | Indicators                             |           |     |       |
| Dashboard Checks           |  |           |     |       |
| G                          | Engine Management Light                |           |     |       |
| G                          | ABS Warning Light                      |           |     |       |
| G                          | Brake Wear Indicator Light             |           |     |       |
| G                          | Oil Warning Light                      |           |     |       |
| G                          | Airbag Waring Light                    |           |     |       |
| Interior Checks            |  |           |     |       |
| G                          | 2 Keys                                 |           |     |       |
| G                          | Locking Wheel Nut                      |           |     |       |
| G                          | Handbook                               |           |     |       |

CUSTOMER DETAIL

INTERNAL

H  
Tel M  
W

VEHICLE DETAIL

Make Volkswagen  
Model Golf  
Registration WF19CZW  
Chassis No WVVWZZZAUZKP065797  
Mileage 28312

VHC NO 5924  
Date 09/06/2025  
Service Advisor  
MOT Due 20/03/2026  
Inspected By Andy Underhill  
VHC Type PDI Check

| Comments / Recommendations |                                     | Net  | VAT  | Total |
|----------------------------|-------------------------------------|------|------|-------|
| G                          | Vehicle has Fuel (20 miles minimum) |      |      |       |
| G                          | Tyre Repair Kit                     |      |      |       |
| G                          | Tool Kit                            |      |      |       |
| Documentation              |                                     |      |      |       |
| G                          | V5 Registration Certificate         |      |      |       |
| G                          | Valid MOT                           |      |      |       |
| G                          | HPI Checked                         |      |      |       |
| G                          | No Outstanding Safety Recalls       |      |      |       |
| Total                      |                                     | 0.00 | 0.00 | 0.00  |

| Tyres       | Tread (mm) |     |  | Manufacturer | Size | Comments/Recommendations |
|-------------|------------|-----|--|--------------|------|--------------------------|
| G N/S Front |            | 4.0 |  |              |      |                          |
| G N/S Rear  |            | 5.0 |  |              |      |                          |
| G O/S Front |            | 4.0 |  |              |      |                          |
| G O/S Rear  |            | 5.0 |  |              |      |                          |
| G Spare     |            | 3.0 |  |              |      |                          |

Photos

2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Tyre Repair Kit - Image 1 of 1



**Customer Signature**\_\_\_\_\_ The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.