# **Steve Clarke Garages Ltd**

## **Vehicle Health Check**

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 1889

Make Hyundai Date 29/09/2021

 H
 Model
 i10
 Service Advisor

 Tel
 M
 Registration
 WF18NVS
 MOT Due

W Chassis No NLHA851CMJZ421372 Inspected By Charlie Wardale

Mileage 10753

		Comments / Recommendations	Net	VAT	Total
E	ngine Bay				
G	Battery State of Health				
G	Coolant Level				
G	Power Steering Fluid Level				
G	Brake Fluid Level	223 degrees			
G	Washer Bottle Level				
G	Engine Oil Level				
G	Oil Contamination				
E	ngine Running		,		
G	Starts				
G	Engine Running				
G	Engine Smoking				
G	Engine Bay Noise				
G	Exhaust Condition (no leaks				
	& secure)				
D	ynamic Operations				
G	Brake Test				
G	Hand Brake Test				
G	Static Gear Selection (engine running)				
G	1st & Reverse Drive Test				
G	Clutch / Auto Drive take up				
G	Steering				
G	Suspension Noise / Ride Height				
G	Aircon (excl. temp & gassing)				
Α	Sat Nav (excl.functionality)	N/a			
G	Ice Operates (excl. functionality)				
G	Central Locking (excl. Key Fob)				
G	Windows				
G	Wipers/Washers				
Α	Roof Electrics	N/a			
G	Horn				
G	Lights				
G	Indicators				
D	ashboard Checks				
G	Engine Management Light				
G	ABS Warning Light				
G	Brake Wear Indicator Light				
G	Oil Warning Light				
G	Airbag Waring Light				
ln	terior Checks		1	•	
G	2 Keys				
Α	Locking Wheel Nut	N/a			
G	Handbook				
G	Vehicle has Fuel (20 miles				
	minimum)				

# **Steve Clarke Garages Ltd**

### **Vehicle Health Check**

**CUSTOMER DETAIL VEHICLE DETAIL** VHC NO 1889

> Make Hyundai Date 29/09/2021

Model i10 Н Service Advisor Registration WF18NVS Tel **MOT Due** 

Chassis No Inspected By **Charlie Wardale** W NLHA851CMJZ421372

> 10753 Mileage

		Comments / Recommendations	Net	VAT	Total
Α	Tyre Repair Kit	N/a			
G	Tool Kit				
D	ocumentation				
G	V5 Registration Certificate				
G	Valid MOT	08/06/22			
G	HPI Checked				
G	No Outstanding Safety Recalls				
		Total	0.00	0.00	0.00


Tyres	Tread (mm)	Manufacturer Size	Comments/Recommendations	
G N/S Front	6.0			
G N/S Rear	6.0			
G O/S Front	5.0			
G O/S Rear	6.0			
G Spare	5.0			

#### **Photos**

M

2 Keys - Image 1 of 1







Vehicle has Fuel (20 miles minimum) -



Customer Signature\_

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.