

Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL

Mr Paul Gale

H

Tel M 0

W

VEHICLE DETAIL

Make Mercedes-Benz

Model SLK

Registration NL16ZVO

Chassis No WDD1724342F124860

Mileage 44117

VHC NO

1984

Date 19/01/2022

Service Advisor

MOT Due

Inspected By Charlie Wardale

Comments / Recommendations		Net	VAT	Total
Engine Bay				
G	Battery State of Health			
G	Coolant Level			
G	Power Steering Fluid Level			
G	Brake Fluid Level	201 degrees		
G	Washer Bottle Level			
G	Engine Oil Level			
G	Oil Contamination			
Engine Running				
G	Starts			
G	Engine Running			
G	Engine Smoking			
G	Engine Bay Noise			
G	Exhaust Condition (no leaks & secure)			
Dynamic Operations				
G	Brake Test			
G	Hand Brake Test			
G	Static Gear Selection (engine running)			
G	1st & Reverse Drive Test			
G	Clutch / Auto Drive take up			
G	Steering			
G	Suspension Noise / Ride Height			
G	Aircon (excl. temp & gassing)			
G	Sat Nav (excl.functionality)			
G	Ice Operates (excl. functionality)			
G	Central Locking (excl. Key Fob)			
G	Windows			
G	Wipers/Washers			
G	Roof Electrics			
G	Horn			
G	Lights			
G	Indicators			
Dashboard Checks				
G	Engine Management Light			
G	ABS Warning Light			
G	Brake Wear Indicator Light			
G	Oil Warning Light			
G	Airbag Waring Light			
Interior Checks				
G	2 Keys			
G	Locking Wheel Nut			
G	Handbook			
G	Vehicle has Fuel (20 miles minimum)			

Steve Clarke Garages Ltd

Vehicle Health Check

CUSTOMER DETAIL			VEHICLE DETAIL		VHC NO	1984
Mr Paul Gale			Make	Mercedes-Benz	Date	19/01/2022
H			Model	SLK	Service Advisor	
Tel M 0			Registration	NL16ZVO	MOT Due	
W			Chassis No	WDD1724342F124860	Inspected By	Charlie Wardale
			Mileage	44117		

Comments / Recommendations		Net	VAT	Total
G Tyre Repair Kit				
A Tool Kit	N/a			
Documentation				
G V5 Registration Certificate				
G Valid MOT	16/01/23			
G HPI Checked				
G No Outstanding Safety Recalls				
Total		0.00	0.00	0.00

Tyres	Tread (mm)			Manufacturer	Size	Comments/Recommendations
G N/S Front		4.0				
G N/S Rear		5.0				
G O/S Front		6.0				
G O/S Rear		6.0				
G Spare						

Photos

2 Keys - Image 1 of 1



Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Vehicle has Fuel (20 miles minimum) -



Tyre Repair Kit - Image 1 of 1



V5 Registration Certificate - Image 1 of 1



Customer Signature

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.