Steve Clarke Garages Ltd

PDI Check

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 5069

INTERNAL Make Hyundai Date 2024-11-12

H Model i20 Service Advisor

 Tel
 M
 Registration
 LD71YMC
 MOT Due
 27/09/2025

 W
 Chassis No
 NLHBN51GVMZ093750
 Inspected By
 Andy Underhill

Mileage 7426 VHC Type PDI Check

	Comments / Recommendations	Net	VAT	Total
Engine Bay				
G Battery State of Health				
G Coolant Level				
G Power Steering Fluid Level				
G Brake Fluid Level				
G Washer Bottle Level				
G Engine Oil Level				
G Oil Contamination				
Engine Running		l .	1	.1
G Starts				
G Engine Running				
G Engine Smoking				
G Engine Bay Noise				
G Exhaust Condition (no leaks				
& secure)				
Dynamic Operations				
G Brake Test				
G Hand Brake Test				
G Static Gear Selection (engine running)				
G 1st & Reverse Drive Test				
G Clutch / Auto Drive take up				
G Steering				
G Suspension Noise / Ride Height				
G Aircon (excl. temp & gassing)				
G Sat Nav (excl.functionality)				
G Ice Operates (excl. functionality)				
G Central Locking (excl. Key Fob)				
G Windows				
G Wipers/Washers				
G Roof Electrics				
G Horn				
G Lights				
G Indicators				
Dashboard Checks				
G Engine Management Light				
G ABS Warning Light				
G Brake Wear Indicator Light	_			
G Oil Warning Light				
G Airbag Waring Light				
Interior Checks				
G 2 Keys				
G Locking Wheel Nut				
G Handbook			1	1

Steve Clarke Garages Ltd

Model

PDI Check

Service Advisor

CUSTOMER DETAIL VEHICLE DETAIL VHC NO 5069

i20

Make Hyundai **INTERNAL** Date 2024-11-12

LD71YMC Tel Registration **MOT Due** 27/09/2025 M

> Chassis No **Andy Underhill** NLHBN51GVMZ093750 Inspected By VHC Type **PDI Check** Mileage 7426

		Comments / Recommendations	Net	VAT	Total
G	Vehicle has Fuel (20 miles minimum)				
G	Tyre Repair Kit				
G	Tool Kit				
D	ocumentation				
G	V5 Registration Certificate				
G	Valid MOT				
G	HPI Checked				
G	No Outstanding Safety Recalls				
		Total	0.00	0.00	0.00

Tread (mm)	Manufacturer Size	Comments/Recommendations
6.0		
6.0		
6.0		
6.0		
	6.0 6.0 6.0	6.0

Photos

Н

W





Locking Wheel Nut - Image 1 of 1



Handbook - Image 1 of 1



Customer Signature

The work outlined in this report has been brought to my attention

This report and any costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Estimate valid for 30 days from inspection.