

Reg Number

YR69OJP

Inspection Date: 18/09/23

GT Automotive has fully inspected this vehicle, covering:

Body Exterior Fittings

Exterior fittings such as the registration plate, bonnet hinges, bonnet catch, door locks and the windscreen



Interior Fittings

Air vents, boot and tailgate operation, mirrors, seatbelts and buckles



Engine Compartment

Engine noise at idle and on road test, levels for brake fluid, engine oil, power steering (when applicable) and coolant. We also check for excessive smoke, hoses, turbo noise and the engine mounts



Electric Systems

We check the electrical systems such as the exterior lights, radio operation, air conditioning operation (temp checked), 12v battery condition, window and wiper operations, number plate lights



Suspension + Steering inc Underbody

We check the following items for play and damage in the following parts. The anti roll bars, shock absorbers, springs, ball joints, the condition of the subframe underneath, wheel bearings



Clutch and gearbox/final drive

Driveshafts, the clutch operation, CV joints and check for leaks



Fuel System

Check for visible leaks on the system and the fuel filter housing



Brakes Wheels and Tyres

We check the brake pads and discs for wear, including excessive corrosion. We check that all tyres are above the legal limit (1.6mm) and replace if 2mm or below



Road Test



Warning Lights

We check that no warning lights are on the dash before, during and after test drives



Additional Notes

Full service history
New clutch fitted 58,231
MOT expires 7/10/24